

12 Feb 02 RAF Lakenheath, UK	F-15E	USAFE 48 FW, RAF Lakenheath, UK	FACTS: Mishap aircraft (MA) was #2 of two-ship basic surface attack mission. Upon takeoff, MA observed airborne with large flame exiting #1 engine. MA returned to base and crew ground egressed. Engine sustained significant internal damage. STATUS: <u>IAW AFI 51-503, Chap 11, Abbreviated AIB to be convened.</u>
---	-------	--	--

FIX